

Aspect Weekly Update

Monroe Street Apartments Development (Former LDM Site - ECSI #887)

WEEK 7: NOVEMBER 29 - DECEMBER 3, 2021


ON-SITE ACTIVITIES

- Lauzon continued grading and fill placement on Parcel 1, especially in area of Building 1.
- LMC/Lauzon made progress decommissioning manhole in Parcel 1 and abandoning the sewer line under Parcels 1 and 2 by filling with CDF. Sewer line abandonment will continue next week.
- Removed fencing around West (and North) boundary of Parcel 2
 and built a construction road entering east of Parcel 2 and
 exiting northwest on Parcel 1 to facilitate Parcel 1 Building 1
 prep.

- Aspect was on site 11/30 and 12/2 to provide input during site construction.
- Partner visited the site on 12/1.
- 18 well decommissioning waste drums were removed from Parcel 2 by WasteXpress on 12/2.
- No analytical samples were collected this week. TCLP metals analytical results from well decommissioning waste drum sample were received from Apex lab.
- Waste transported off site this week included Parcel 1 strippings and Parcel 2 IDW drums.

PLAN VIEW PROGRESS

Constructed road across Parcel 2 temporary cap to facilitate construction access to Building 1 area on Parcel 1.



KEY ONSITE ACTIVITIES PLANNED FOR NEXT TWO WEEKS

- Continue backfill of abandoned sewer line beneath Parcel 1 and Parcel 2.
- Continue grading and fill placement on Parcel 1, especially in area of Building 1.
- Continue preparing pad for Building 1 on Parcel 1.
- LMC job trailer to be delivered to site.
- Potential offsite disposal of geotechnically unsuitable Parcel 2
 mound soil after communication with DEQ. Goal to minimize
 offsite disposal by Lauzon making use of suitable mound soil and
 excavated soil stockpile as Parcel 2 landscape fill beneath the
 clean fill cap, where possible.
- Concrete and steel debris from well decommissioning to be removed from site by Waste Management after profiling. Waiting on final profile from WM.

UPCOMING DELIVERABLES to DEQ and ACTION ITEM REQUESTS

 Aspect is preparing for the 2021 Annual Protectiveness Review reporting process and Winter 2022 Semiannual groundwater monitoring.

PHOTOS



11/30/21 Parcel 1 grading, looking east.



12/2/21 Drum pickup on Parcel 2.